



WARNING

POTENTIALLY HAZARDOUS SITUATION
THAT COULD RESULT IN **DEATH OR
SERIOUS INJURY.**

SAFETY ALERT

Alert No.: SAF00708

Date: November 28, 2007

Title: Winch Key Replacement

Product Series /Model: 8000 and 10000 Series Cranes built prior to October 26, 2006 (Check date on crane inspection decal)

Summary: Maintainer has received reports of winch drum key failures in the 8000 and 10000 Series cranes. If the winch drum key fails the winch drum can rotate freely, unexpectedly dropping any load suspended by the crane. **THIS FAILURE COULD RESULT IN DEATH OR SERIOUS INJURY TO PERSONNEL OR DAMAGE TO EQUIPMENT.** This Safety Alert supersedes earlier Service Bulletins SB00702 and SB00703.

Action: Immediately replace the winch key with a replacement supplied by Maintainer Corporation.

Procedure:

1. Immediately complete and return the Customer Information Form included with this mailing.
2. The new winch drive key will be shipped via UPS Overnight directly from Maintainer, free of charge.
3. Install the supplied parts using the instructions and procedure provided.
4. The estimated time to replace the winch key is 1 ½ hours. Maintainer will issue payment of \$100.00 for the installation of the new winch drive key upon receipt of a signed Labor Claim Form confirming that the installation has been successfully completed.

Contact: Doug Schrader, Customer Service
1-800-831-8588 or
dschrader@maintainer.com



Maintainer Corporation of Iowa, Inc.
1701 S. 2nd Ave, Box 349
Sheldon, IA 51201
P: 800.831.8588 F: 712.324.3526
www.maintainer.com